



Original drain holes

1/4 Tube with crimped end



Drilled through existing drain holes into side of tube after tube was mounted and fibreglassed in.

Hose clamp missing from photo

